



InterLink Systems, Inc.

5116 Bissonnet #341, Bellaire, TX 77401

Telephone and Fax: (713) 663-6361

jamesmcadams@alumni.rice.edu

**Technical Notes on
16D BOP Accumulator Sizing
and Performance Tool
Revision 1.11 – 12 September, 2014**

This release incorporates small changes from Revision 1.10, the last published revision.

Formatting Errors

The Performance Table and the Liquid Volumes sections could print down over the footer if you include a lot of equipment in the stack. They now format themselves properly.

If you used a super long file name, it could overwrite the page number in the footer. This version will try progressively smaller fonts down to 8 point in an effort to avoid messing up the page number.